

Vehicle diagnostic report



Shop Name: hardlock.org.ua
Address: г.Минск
Telephone: +375447662055
Email : tech@asbgroup.by
Fax:

Make: SKODA
Model:
Year: 2021
VIN: XW8LC6NUXMH208871
ODO: 1020 km
Vehicle Software Version: V28.15
Diagnostic Application Version: V3.11.008
Test Time: 2021-05-01 20:41:02
Diagnostic path: Health Report



Diagnostic Result

Fault (4)

19 Gateway	(1)	Abnormal
	U10A400 Electronic Steering Column Lock Control Module - No Communication	passive/abiogenesis
B7 Access Startsystem Interface	(3)	Abnormal
	B11A512 Term S - Short Circuit To B+	passive/abiogenesis
	B114812 Terminal 15 - Short Circuit To B+	passive/abiogenesis
	B11D612 Terminal 15 Redundancy - Short Circuit To B+	passive/abiogenesis
01 Engine Control Module 1	(4)	Abnormal
	P061600 Starter Relay Circuit Low	passive/abiogenesis
	P304800 Activation Starter Relay 2 - Short Circuit To Ground	passive/abiogenesis
	P305200 Starter Activation, Return Message Terminal 50-Short Circuit To B+	passive/abiogenesis

P332500 Power Supply Terminal 15-Implausible

passive/abiogenesis

02 Transmission Control (1)
Module

Abnormal

P170100 Transmission Control Unit Locked

passive/abiogenesis

Normal

(17)

76 Parking Assistance	Normal
09 Central Electrics	Normal
22 All Wheel Control	Normal
44 Steering Assistance	Normal
03 Brakes 1	Normal
17 Dash Board	Normal
15 Airbag	Normal
6D Deck Lid Control Unit	Normal
20 High Beam Assistance	Normal
2B Steering Column Locking	Normal
08 Air Conditioning	Normal
42 Door Electronics Driver Side	Normal
52 Door Electronics Passenger Side	Normal
13 Adaptive Cruise Control	Normal
75 Telematics Communication Unit	Normal
5F Information Control Unit 1	Normal
4B Multifunction Module	Normal
Remark: after dz	